

General Environmental Incident Summary

Incident: 1267 **Notice:** 7/9/2010 1114 **Occurred:** 7/7/2010 1700
DEM Incident No: **No Further Action:** ☒
Responsible Party: Unknown
County: Burleigh
Twp Rng Sec Qtr: 140 80 0
Lat Long + Method: 46.93270 -100.77200 Navigation quality GPS
Location Description: Highway 83, north bound lane on right wheel track between points 46.9327, -100.7720 and 46.9685, -100.7893; AH - 10/16/2012 - This area involves Sections 9, 16 and 21.
Submitted By Info: Steven Krentz

Received By Info:

Contact Info:

Unknown
Unknown ND

Affected Medium:

Near. Occupied Bldg: 500 Feet
Type of Incident: Appears to be discharge from tanker vehicle onto highway.

Release Contained:

Reported to NRC: Unknown

Contaminant: Unknown

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Appears to be a discharge from a north bound vehicle and based on quality, probably a tanker truck. You can see where at about 123 Ave, they pulled over and substance adhered to gravel along road.

Risk Evaluation:

Potential Env. Impacts:

Action Taken/Planned:

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 10/16/2012 ***Status:*** Comment

Author: Harries, Alison

Notes:

Section will remain set to zero because multiple sections are involved in release.

Updated Volume: None at the time of this update

Date: 10/4/2018 ***Status:*** Inspection

Author: Stockdill, Scott

Notes:

Arrived on location 11:09 10/4/2018.

No sign of remaining contaminants or contamination at the described location.

No follow-up is necessary.

Updated Volume: None at the time of this update